



Nº 3 092

CONTENTS

	Page
Preface	5
Introduction	7
1. Relevant parameters	9
1.1 Automatic film processors	9
1.1.1 Definition of performance and method of measurement	9
1.1.2 Additional practical factors	10
(a) Specific gravity and pH	10
(b) Temperature	10
(c) Residual hypo testing	11
(d) Silver recovery	12
(e) Transport speed	12
(f) Replenishment rates	12
1.1.3 Setting up an automatic film processor	12
1.2 X-ray films, screens and cassettes	13
1.2.1 Film-screen characteristic curve	13
1.2.2 Image quality	15
1.2.3 Additional practical aspects	15
(a) General condition of cassettes and screens	15
(b) Film-screen contact	16
(c) Relative screen sensitivity	16
1.3 Illuminators and viewing room conditions	16
1.4 Darkroom and film storage conditions	17
1.5 Automatic exposure control systems	17
2. Measurements	18
2.1 Automatic film processors	18
2.1.1 Setting up an automatic film processor	18
2.1.2 Additional practical measurements	18
2.1.3 Practical aspects in relation to several processors	20
2.1.4 Daily monitoring of processor performance	20
2.2 X-ray films, screens and cassettes	21
2.2.1 Film-screen characteristic curve	21
2.2.2 Image quality	25
2.2.3 Additional practical aspects	25
2.3 Illuminators and viewing room conditions	26
2.4 Darkroom and film storage conditions	27
2.5 Automatic exposure control systems	27
2.6 Measurement programme	28
Appendix I Test solution for residual hypo testing	30
Appendix II Test object for producing characteristic curves	30
Appendix III Test objects for assessing film-screen image quality	30
References	32